

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190528-E469651  
**Report Reference** E469651-20141023  
**Issue Date** 2019-MAY-28

**Issued to:** LEGRAND  
Boite Postale 36  
72140 Sille Le Guillaume FRANCE

**This certificate confirms that representative samples of** CABLE TRAYS, METAL  
REFER ADDENDUM PAGE FOR MODELS

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** Sections 392.60(A) and 392.60(B) of NFPA 70 NATIONAL ELECTRICAL CODE WITH AMD

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190528-E469651  
**Report Reference** E469651-20141023  
**Issue Date** 2019-MAY-28

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

## Series P31 Cable Trays

350210, 350212, 350213, 350214; Joint Connector Models 341221, 350042, 350057; Tray Covers, Models 341290, 341293, 341294, 341295 and 350260, 350263, 350264, 350265. All Cable Trays models may be provided with prefix "UL".

## Associated Fittings

340750, 340753, 340754, 340770, 340773, 340774, 340775, 340800, 340803, 340804, 340805, 340810, 340813, 340814, 340780, 340783, 340784, 340785, 340790, 340793, 340794, 340795, 340820, 340823, 340824, 340833, 340834, 341173, 350160, 350162, 350163, 350164, 350170, 350172, 350173, 350174, 350220, 350222, 350223, 350224, 350240, 350242, 350243, 350244; End-Caps, Models 341156, 341159, 341160. Divider Model 231201. All Associated Fittings models may be provided with prefix "UL".

## Fitting Covers

341290, 341293, 341294, 341390, 341393, 341394, 341400, 341403, 341404, 341410, 341413, 341414, 341415, 341420, 341423, 341424, 341425, 341430, 341433, 341434, 341435, 341440, 341443, 341444, 341445, 350180, 350182, 350183, 350190, 350192, 350193, 350230, 350232, 350233, 350250, 350252, 350253. All Fitting Covers models may be provided with prefix "UL".

## Bonding Jumper

TFEB-1-F. May be provided with prefix "UL".

CABLE TRAY GROUNDING TERMINALS, Cat. Nos. 585357, 585367, 585377

PERFORATED TRAY M/F, Cat. Nos. 480045, 480046, 480047, 485048, 485049, 480050, 480051, 482145, 482146, 482147, 485248, 485249, 482050, 482051


90° HORIZONTAL BEND, Cat. Nos. 480907, 480908, 480909, 482907, 482908, 482909

PERFORATED 90° HORIZONTAL BEND, Cat. Nos. 480910, 480911, 482910, 482911, 481188, 481189, 483188, 483189

VERTICAL INSIDE 90° RISER, Cat. Nos. 480972, 480973, 480974, 480975, 480976, 482972, 482973, 482974, 482975, 482976

PERFORATED VERTICAL INSIDE 90° RISER, Cat. Nos. 483977, 483978, 483984, 483985.

EQUAL TEE, Cat. Nos. 481096, 481097, 481098, 481099, 481110, 482096, 483097, 483098, 483099, 483100



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190528-E469651  
**Report Reference** E469651-20141023  
**Issue Date** 2019-MAY-28

EQUAL TEE PERFORATED, Cat. Nos. 483252, 483253, 483452, 483453

TEE BRANCH, Cat. Nos. 480108, 480109, 480118, 480119, 480126, 480127, 480128, 482108, 482109, 482118, 482119, 482126, 482127, 482128

VERTICAL OUTSIDE 90° RISER, Cat. Nos. 481031, 481032, 481033, 481034, 481035, 482031, 482032, 482033, 482034, 482035

PERFORATED VERTICAL OUTSIDE 90° RISER, Cat. Nos. 483036, 483037, 483336, 483337

UNIVERSAL DIVIDER, Cat. Nos. 481516, 483516

END CAP, Cat. Nos. 481518, 481519, 481520, 481521, 481522, 481523, 481524, 483518, 483519, 483520, 483521, 483522, 483523, 483524

VERTICAL TEE, Cat. Nos. 480310, 480311, 480312, 481831, 481832, 481833, 481834

VERTICAL INSIDE 90° RISER, Cat. Nos. 480810, 480811, 480812, 480813, 480814, 482810, 482811, 482812, 482813, 482814

PERFORATED VERTICAL INSIDE 90° RISER, Cat. Nos. 480815, 480816, 480817, 482815, 482816, 482817. Refer to Ill. CF03832 for additional details and dimensions.

EQUAL TEE, Cat. Nos. 480790, 480791, 480792, 480793, 480794, 482790, 482791, 482792, 482794, 481793

EQUAL TEE PERFORATED, Cat. Nos. 480795, 480796, 480797, 482795, 482796, 482797

PERFORATED TRAY M/F AUTOMATIC, Cat. Nos. 480110, 480111, 480112. M/F AUTOMATIC end construction


PERFORATED EMBOSSED TRAY M/F AUTOMATIC, Cat. Nos. 480113, 480114, 480115, 480116, 480117

SOLID BOTTOM TRAY M/F AUTOMATIC, Cat. Nos. 481120, 481121, 481122, 481123, 481124

SOLID BOTTOM EMBOSSED TRAY M/F AUTOMATIC, Cat. Nos. 481125, 481126, 481127

PERFORATED TRAY M/F AUTOMATIC MBR, Cat. Nos. 481823, 481824, 481825, 481826, 481827

PERFORATED TRAY M/F AUTOMATIC CPC, Cat. Nos. 481260, 481261, 481262, 481263, 481264, 481265



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190528-E469651  
**Report Reference** E469651-20141023  
**Issue Date** 2019-MAY-28

PERFORATED TRAY M/F AUTOMATIC, Cat. Nos. 487111, 487113, 487114. M/F AUTOMATIC end construction

HORIZONTAL BEND 45° CPC, Cat. Nos. 487840, 487841, 487842, 487843, 487838, 487839

PERFORATED TRAY M/F, Cat. Nos. 482110, 482111, 482112, 482113, 482114, 482115, 482116, 482117, 481219, 481220, 481221, 481222, 481223, 481224, 481225, 481226

SOLID BOTTOM TRAY M/F, Cat. Nos. 482556, 482549, 482550, 482551, 482552, 482553, 482554, 482555, 480719, 480720, 480730, 480740, 480760, 480770, 480780, 480700

PERFORATED TRAY M/F AUTOMATIC LIGHTING, Cat. Nos. 487000, 487001, 487002, 487003, 487004, 487005

SYMETRICAL PERFORATED TRAY, Cat. Nos. 480561, 480562, 480563, 480564, 480565, 480566, 480567, 480568, 480571, 480572, 480573, 480574, 480575, 480576, 480577, 480578

SYMETRICAL SOLID BOTTOM TRAY, Cat. Nos. 480301, 480302, 480303, 480304, 480305, 480306, 480307, 480308, 481061, 481062, 481063, 481064, 481065, 481066, 481067, 481069

TEE BRANCH, Cat. Nos. 481780, 481781, 481782, 481783, 481784, 481785, 481786, 481787, 482780, 482781, 482782, 482783, 482784, 482785, 482786, 482787

ADJUSTABLE HORIZONTAL BEND, Cat. Nos. 481770, 481771, 481772, 481773, 481774, 481775, 481776, 481777

VERTICAL OUTSIDE 90° RISER, Cat. Nos. 480800, 480801, 480802, 480803, 480804, 482800, 482801, 482802, 482803, 482804

PERFORATED VERTICAL OUTSIDE 90° RISER, Cat. Nos. 480805, 480806, 480807, 482805, 482806, 482807

HORIZONTAL BEND 90°, Cat. Nos. 480750, 480751, 480752, 482750, 482751, 482752


PERFORATED HORIZONTAL BEND 90°, Cat. Nos. 480753, 480754, 480755, 480756, 480757, 482753, 482754, 482755, 482756, 482757

VERTICAL TEE, Cat. Nos. 480141, 480142, 480143, 480144, 480145

HORIZONTAL BEND 30°, Cat. Nos. 487804, 487805, 487806, 487807, 487808, 487809

HORIZONTAL BEND 15°, Cat. Nos. 487800, 487801, 487802, 487803, 487798, 487799

VERTICAL BEND ("IN/OUT") 45°, Cat. Nos. 487970, 487972, 487973, 487974, 487968, 487969



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190528-E469651  
**Report Reference** E469651-20141023  
**Issue Date** 2019-MAY-28

UNIVERSAL BRANCH, Cat. Nos. 481173, 482273

ER COUPLER, Cat. Nos. 341220, 343220

UNIVERSAL DIVIDER, Cat. Nos. 483428, 480428

UNIVERSAL COUPLER EDU, Cat. Nos. 481169, 482169

REDUCED EDU COUPLER, Cat. No. 487980

END CAP, Cat. Nos. 481156, 481157, 481158, 481159, 481160, 483156, 483157, 483158, 483159, 483160

END CAP REDUCER, Cat. Nos. 481161, 482161

QUICK COUPLER ("ECLIC"), Cat. No. 480221

ACCESSORY/FITTING COUPLER, Cat. Nos. 341562, 343562

STRAIGHT COUPLER ("EP50-60 PIANO"), Cat. Nos. 341213, 343213

VERTICAL INSIDE 90° RISER, Cat. Nos. 481995, 481996, 481997, 481998, 482995, 482996, 482997, 482998

PERFORATED VERTICAL INSIDE 90° RISER, Cat. Nos. 483181, 483182, 483183, 483411, 483412, 483413

EQUAL TEE, Cat. Nos. 481800, 481801, 481802, 481803, 482280, 482281, 482282, 482283


PERFORATED TRAY M/F, Cat. Nos. 480068, 480069, 481070, 481071, 480072, 480073, 480107, 482068, 482069, 482170, 482171, 482072, 482073, 482106

SOLID BOTTOM TRAY M/F, Cat. Nos. 480030, 480031, 480032, 480033, 480092, 480093, 480106, 482088, 482089, 482090, 482091, 482092, 482093, 482107

EQUAL TEE PERFORATED, Cat. Nos. 481470, 481471, 481472, 483470, 483471, 483472

TEE BRANCH, Cat. Nos. 480530, 480531, 480532, 480533, 480534, 480535, 480536, 482439, 482441, 482445, 482446, 482498, 482499, 482500

PERFORATED VERTICAL OUTSIDE 90° RISER, Cat. Nos. 483504, 483505, 483506, 483326, 483327, 483328



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190528-E469651  
**Report Reference** E469651-20141023  
**Issue Date** 2019-MAY-28

SOLID BOTTOM VERTICAL OUTSIDE 90° RISER, Cat. Nos. 481054, 481055, 481056, 481057, 482010, 482011, 482012, 482013

HORIZONTAL BEND 90°, Cat. Nos. 480930, 480931, 482930, 482931

PERFORATED HORIZONTAL BEND 90°, Cat. Nos. 480932, 480933, 482932, 482933, 483319, 483320, 483321, 483206, 483207, 483208

ER COUPLER, Cat. Nos. 341220, 343220

UNIVERSAL DIVIDER, Cat. Nos. 481657, 483657

END CAP, Cat. Nos. 481659, 481660, 481661, 481662, 481663, 481664, 480737, 483659, 483660, 483661, 483662, 483663, 483664, 482737

ACCESSORY/FITTING COUPLER, Cat. Nos. 341620, 343620

STRAIGHT COVER, Cat. Nos. 341290, 341291, 341292, 341293, 341294, 341295, 341296, 341297, 340190, 340191, 340192, 340193, 340194, 340195, 340196, 340197

INSIDE 90° RISER COVER, Cat. Nos. 480889, 480890, 480891, 480892, 480893, 480896, 480897, 480898, 482889, 482890, 482891, 482892, 482893, 482896, 482897, 482898

EQUAL TEE COVER, Cat. Nos. 480880, 480881, 480882, 480883, 480884, 480885, 480886, 480887, 482880, 482881, 482882, 482883, 482884, 482885, 482886, 483377

TEE BRANCH COVER, Cat. Nos. 480502, 480503, 480504, 480505, 480728, 480745, 480746, 480747, 482502, 482503, 482504, 482505, 482728, 482745, 482746, 482747


ADJUSTABLE HORIZONTAL BEND COVER, Cat. Nos. 480094, 480095, 480096, 480097, 480098

VERTICAL OUTSIDE 90° RISER COVER ("TWIST"), Cat. Nos. 489000, 489001, 489002, 489003, 489004, 489005, 489006, 489007, 489020, 489021, 489022, 489023, 489024, 489025, 489026, 489027

VERTICAL OUTSIDE 90° RISER COVER, Cat. Nos. 480808, 480809, 480818, 480819, 480827, 480828, 480829, 482799, 482808, 482809, 482818, 482819, 482827, 482828, 483829, 480799

HORIZONTAL BEND 90° COVER, Cat. Nos. 480862, 480863, 480864, 480865, 480866, 480867, 480868, 480869, 482862, 482863, 482864, 482865, 482866, 482867, 482868, 483314

HORIZONTAL BEND 15°, 30°, 45° COVER, Cat. Nos. 487910, 487912, 487913, 487914, 487920, 487922, 487923, 487924, 487930, 487932, 487933, 487934, 487928, 487929, 487918, 487919, 487908, 487909



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE


**Certificate Number** 20190528-E469651  
**Report Reference** E469651-20141023  
**Issue Date** 2019-MAY-28

VERTICAL BEND ("IN/OUT") COVER, Cat. Nos. 481090, 481091, 481092, 481093, 481094, 481095

UNIVERSAL BRANCH COVER, Cat. Nos. 341174, 343174

STRAIGHT COVER, Cat. Nos. 342170, 342171, 342172, 342152, 342153, 342154, 342155, 342156

STRAIGHT COUPLER ("EP75-100 PIANO"), Cat. Nos. 341216, 343216



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

